
FIG.1






FIG.2






FIG. 3








FIG.6




FIG.7





FIG.8








FIG. 10

CH2	CH1	СНО	DAR				A/D conversion
			A3	A2	A1_	A0	A/D Conversion
0	0	0	0	0	0	0	ANO Input Conversion
0	0	1	0	0	1	0	AN1 Input Conversion
0	1	0	0	1	0	0	AN2 Input Conversion
0	1	1	0	1	1	0	AN3 Input Conversion
1	0	0	1	0	0	0	AN4 Input Conversion
1	. 0	1	1	0	1	0	AN5 Input Conversion
1	1	0	1	1	0	0	AN6 Input Conversion
1	1	1	1	1	1	0	AN7 Input Conversion

FIG. 11




FIG. 12




FIG. 13




FIG. 14









FIG. 15











SAR

 $_{3B}\bar{J}$ 

FIG. 20

